

(8)

INSPECTION OF FUNCTIONING STATUS OF RAIN WATER RECHARGE STRUCTURES IN COMPLIANCE OF NGT ORDER IN M.A. 808 OF 2013 IN APPLICATION NO. 94/2013 DATED 4.7.2014

Date of Inspection: 30.3.2015
District: South West District

Name & Address of RWA: Hotel Hyatt Regency, Bokaaji, Kone place (Asian Hotels Limited), New Delhi.

Location of RWH structures: 3 structures with tube well type.

No. of RWH structures/ Recharge wells: 3 structures with tube well type.

S.No	Catchment Area (Approx.)	Size of recharge pit (Approx.)	Size of Injection Well as per approved design		Design approved by	Condition of filter medium
			Diameter	Depth		
Technical details not available during inspection						

Overall condition of RWH structure: Satisfactory / Not satisfactory Non functional

Suggestions / Remarks, if any: - All 3 structures stagnant water was found, indicating filter media choked. Poss. maintenance - The pit now now tower & swimming pool is completely covered, so not possible to inspect.

Signature
(RWA Representative)
9582894805
30.3.2015

(Inspecting Officer)

Signature
30/3/15
(Inspecting Officer)

Signature
30.3.2015

